


ASSEMBLY INSTRUCTION

MC-11



A




4PCS

B



4PCS

C



1PC




①

Tightening the screws
in clockwise direction




X 1




①

②



X 1



②

